


FIG. 1

EXPRESS MAIL NO. EV 035 054 868 US

BEST AVAILABLE COPY




FIG. 2



Temperature Tracking Device On
32
Time to take Temperature
34
Yes
Take temperature
36
Temperature and time logged
38
Request to access storage unit
authorized user accesses storage unit
40
new log created
42
user # and time added to log
44
Door closed
46
Yes
user # and time added to log
48
No
user places sample
50
user pulls sample
52
sample number added to log
54

FIG. 3

FIG. 4




FIG. 5




FIG. 6

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13





FIG. 14

FIG. 15






FIG. 16




FIG. 17





FIG. 18






FIG. 19




FIG. 20




FIG. 21




FIG. 22

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☑ FADED TEXT OR DRAWING
- ☑ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.
As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.